


## Type 2 Handicap Ramp



## Notes:

- 1. Ramp slope 1:12 maximum 1:15 minimum. 2% max. sidewalk crossfall.
- 2. The concrete finish of the ramp shall have a transverse broomed surface texture rougher than the surrounding sidewalk. The landing shall have a coarse broom finish.

C&G

3. The gutter pan across the route of travel from the ramp to the street shall have a maximum rise of 5%.

Dr. <sub>KT</sub>	No.	Date	Revision	Appr.	Approved By:/	STD PLAN
IXI	1	9/25	UPDATE PER FIRST REVISION			318 1 2 (11
Ch. WS					J. Wally Sandelin 9/25/02	1 1 てつロ
Date					F. Wally Sandelin City Enginee Date	I $I$ $J$ $Z$ $D$ $I$
12\00					R.C.E. 39895	

Midblock-Type 2

-See Note 3